



MEDIA RELEASE

TECHNICAL UPGRADE OF OUR DIGITAL NETWORK ALBURY AND NORTHEAST VICTORIA

On Thursday 3rd March 2011, The WIN Network will be conducting a technical upgrade of our digital network in the Albury Northeast Victoria region.

As a result of this work, some viewers may experience difficulties receiving **WIN**, **GO!** and **GEM**.

Viewers may need to rescan their digital receiver using the remote control. Simply follow these instructions and wait a few minutes. Ensure that the TV is ON when proceeding with the following

Brand	General Instructions (using remote control)
PANASONIC	LCD -Menu (OK) > Set Up (OK) > Tuning Menu (OK) > Auto Tuning (OK) > all channels will be erased > OK Plasma - Menu (OK) > Set Up (OK) > Tuning Menu (OK) > Auto Tuning (OK) > Access (OK) > all channels will be erased > OK
SAMSUNG	D.Menu > Auto Store (picture icon left hand side) > digital tune> Auto Store > start *Ensure you select DTV or DTB to receive digital signal
SHARP	Menu (enter) > Program Set up (enter) > Auto Installation (enter) > Perform Auto Installation > YES
SONY	HOME > Settings (toolbox icon) > Digital Set Up > Digital Tuning > Auto
PIONEER	Function Menu > Others > Set Up > Auto Tuning > OK
NEC	Turn TV off from main on the wall & turn on again. If this still doesn't work, please follow these steps: Menu > Auto arrow across to System (all) > arrow down to Scan/Search/ with arrows pointing right > select right arrow or OK button to activate scan
LG	If older than a year – need Firmware update to fix issues. Tuning Menu or High Booster Menu > Boost Signal OR Menu > System > Auto Program.
OLIN or HALIO	Brand> Set up > Auto Tune > (OK) Call store of purchase or manufacturer technical support for firmware upgrade
TCL	Menu > Install > Auto Install
MYSTAR	Menu > Set Up > Decoder > Scan
DAEWOO	Menu > Install > ATS Broadcast > Digital > Scan (using right arrow)
DSE	Menu > Search Option > Auto Install > Set
COBALT	Select Install Menu to tune
GRUNDIG	Please call help number 1800 509 394
STRONG	Scan > Auto Tune. Call manufacturer for assistance if this still doesn't work
BUSH	Call store of purchase or manufacturer technical support for firmware upgrade
HI SENSE	Auto Install
TOPFIELD	Menu > Installation > Channel Scan > Search – Start
TEAC	Auto Tune. Call store of purchase or manufacturer for firmware upgrade
Set Top Box	Menu > Installation > Auto Tune

Further information:

The WIN Network Publicity
03 53201 366.

